

W2172|5

06-08-2023

08342-0002

CURRITUCK COUNTY MONITORING

EQUIPMENT:

NC VRS

TRIMBLE RS3

WEATHER: CLOUDY

TEMP: 69°F

WIND: 5MPH, ESE

SEAS: FLAT

TIDE: H- 1142

L- 1542

POINT RANGE:

8826 - 1327

FILENAME

060823-CURRITUCKCOUNTY-TOPO-CK

~~060823-CURRITUCKCOUNTY-WADE-CK~~

PT#	DESC	HR	HDE	VDE
8826	RADIORM1	2m	0.108	0.035
8827	CAFFEY		0.052	-0.019
9325	RADIORM1		0.069	0.062

PT#	STA	DESC	HR	COMMENTS
8828	C-120	BERM	2m	BUSH ON LINE
8860		GSR		
8861	C-118	BERM		
8912		GIS		
8915	C-116	BERM		
8934		GIS		
8935	C-114	BERM		
8959		GIS		
8960	C-112	BERM		
8984		BUSH		
8985	C-110	BERM		
9015		GISC		

W172/6

DECK ON LINE, SHOT AROUND

PTH	STA	DESC	HR	COMMENT
9016 9073	C-108	Berm Trees	2M	TREES ON
9074 9117	C-106	Berm GS		TREES @ END
9118 9132	C-107	Berm (BD)		LARGE SHRUBS
9133 9187	C-097	GS BERM		HOUSE ON
9188 9229	C-096	GSC BUSH		GAP LEFT DUE
9230 9284	C-093	GS BERM		SHRUBBERY

060823-CURRITUCK COUNTY - WADE - CK

PTH	STA	DESC	HR	COMMENTS
9285 9323	C-097	Berm SZ	8.28	LOST INT

W217217

LINE, LOST FIXED RTK

OF LINE. COULD NOT FIND ACCESS AROUND

ON DUNE COULD NOT FIND ACCESS THROUGH/AROUND

LINE

TO TALL, DENSE SHRUBS

ON LINE

2 NET CONNECTION, SHORT OF DXF

STOPPED COLLECTING B/C ALL BATTERIES DIED