

2023 - 06 - 07	Currituck/Dare Survey	FM, SL, RLW
0645	Left house	
0655	Getting gas for truck	lice for coodts
0700	Left gas	
0720	check @ ADRIATIC	
0727	check @ Q 261	
0841	C-059	
	water shots	5003 to 5031
0913	C-061	
	water shots	5032 to 5060
0939	C-063	
	water shots	5061 to 5086
1001	C-065	
	water shots	5087 to 5115
1025	C-067	
	water shots	5116 to 5147
1100	C-069	
	water shots	5148 to 5174
1131	C-071	
	water shots	5175 to 5203

vertical: 0.66
horizontal: 0.16 } accuracy requirements

Pde heights
12.21
6.22

* All Pics on Frank's phone label
is in the sand

* 5128 - Bad shot

2023-06-07

Cumtuck L-Pair
Survey

RW, FM, SL

1153 C-073

water shots 5204 to 5230

1216 C-075

water shots 5231 to 5257

1232 C-077

water shots 5258 to 5280

1257 C-079

water shots 5281 to 5306

1314 C-081

water shots 5307 to 5339

1331 C-083

water shots 5340 to 5361

1350 C-085

water shots 5362 to 5388

1405 C-087

water shots 5389 to 5412

* Bumpy

* Add point 5559

* Add points 5556-5558

* Add points 5554-5555

* Add point 5553

Rod height 6.22 ft

* Add points 5551-5552

* Add points 5550

2023-06-07

Commitment/Dave
Survey

RW, FM, SL

1415 C-089

water shots 5413 to 5439

*add points 5548-5549

1434 C-091

water shots 5440 to 5459

*add points 5544-5547

1453 C-093

water shots 5460 to 5475

*add point 5543

1510 C-095

water shots 5476 to 5497

1530 C-097

water shots 5498 to 5512

Rod height 12.21ft